

September 6, 2005

Mr. Joel Vatsky Advanced Burner Technologies P.O. Box 410 271 Route 202/206 Pluckemin, NJ 07978

Dear Mr. Vatsky:

Dissatisfaction with ABT Opti-Flow Burners in IGS Unit 2

This letter is to express the dissatisfaction of Intermountain Power Service Corporation with the performance of ABT's Opti-flow burners that were installed on Intermountain's Unit 2 in the spring of 2004. We are holding ABT at least partially culpable in the recent failure of the Unit 2 F3 burner module and request ABT's assistance in resolving our concerns.

The thermowell design supplied on your burner modules precludes the use of heavy-duty thermocouples (TC's). The bend radius is too tight to allow insertion of the 1/4 inch TC's we specified. The 1/16 inch TC's supplied with the burners are failing prematurely. We are convinced that lack of instrumentation, which would have warned us of a burner fire, contributed to the failure on F3.

We are also experiencing premature wear-related failure of some of our x-vane fuel distributors and elbows at the burner inlet. These failures are unacceptable, especially in burners that are only a little over a year old.

We have suspended plans to replace burners on Unit 1 until we can get these issues resolved. We are requesting assistance from ABT in investigating the cause of these failures and in making them right.

Please contact Mr. Dean Wood at (435) 864-6464 with questions regarding these claims or to set up a plant visit to resolve these issues.


Sincerely.


George W. Cross

President and Chief Operations Officer

Jenge W. Cross

EW/JKH:jmj








ITEM	DESCRIPTION	OPERATION	STROKE
Α	SPIN VANE DRIVE	IN TO OPEN	5 3/4"
В	EXISTING OIL IGNITOR		
С	ABB FIBER OPTIC FLAME SCANNER		
D	DAMPER DRIVE	IN TO OPEN	16"
E	SIGHT TUBE		
	INNER AIR ZONE DAMPER	PUSH TO OPEN	6"
G1	TIP THERMOCOUPLE JUNCTION BOX		
G2	BODY THERMOCOUPLE JUNCTION BOX		



· Korn	ABT Burner Issues Discussion with Staff October 26, 2005 History F3 Burner Fire Melt Down of Coal Nozzle Mod Nozzle Part ABT Out here Call Bonanga Jerry Haske! Gath For the bottom of this is.
CG.	Discussion with Staff October 26, 2005 Dan Howall Call Bonanga (Jerry Haske)
	History F3 Burner Fire Get to the bottom of this is.
	 New Burner Module on Order (delivery in late Nov.) Suspect erosion of nozzle as cause
	 Inspected all 6 burners during U2 tube-leak outage Elbow Damage F1 & F2, eroded through elbows F4 & F5, eroded through inner ceramic lining
	Elbow Damage • F1 & F2, eroded through elbows • F4 & F5, eroded through inner ceramic lining Nozzles • F6; coal erosion at 3:00 and 9:00 o'clock at exit from X-vane Tip Damage Tip Damage
	 Erosion at 11:00 and 1:00 o'clock positions All of F tips E1 E6 C2 & C5
	 Cracking of tip noted in all of F, E1 and C2 Warping of CS at tip on all of F nozzles. (Overheat in out-of-service burners) Thermocouples
	• 1/4" TC's can't be inserted into thermowells • Tight bends • Pipe rather than tubing used • 1/16" TC's substituted • Temperature switches disabled • All Consulting
	 1/16" TC's substituted Temperature switches disabled Alarms added to TC's ABT
	Reply to initial letter
	 Wear parts Velocities higher than design conditions Deny warrantee claims Invited (Tuesday) to site for U2 outage; did not send anyone
	• Have sent them preliminary findings and photos Pulverizer Issues
	Biases High PA Flows (duct pressures up) Feeder biases
	• Improper limits on F-row for 5-burners Options
	Classifiers 8-mill operation — Not likely to succeed per GWC Redesign burners with ABT Change PA flow curves for new rotating throats
	Modify elbows Other suggestions?
	DEW committed to work w/ ABT to find out.
	what our problem is.
	Is PA duct pressure too high?










ITEM	DESCRIPTION	OPERATION	STROKE
Α	SPIN VANE DRIVE	IN TO OPEN	5 3/4"
В	EXISTING OIL IGNITOR		
C	ABB FIBER OPTIC FLAME SCANNER		
D	DAMPER DRIVE	IN TO OPEN	16"
E	SIGHT TUBE		
F	INNER AIR ZONE DAMPER	PUSH TO OPEN	6"
	TIP THERMOCOUPLE JUNCTION BOX		
G2	BODY THERMOCOUPLE JUNCTION BOX		









ITEM	DESCRIPTION	OPERATION	STROKE
A	SPIN VANE DRIVE	IN TO OPEN	5 3/4"
В	EXISTING OIL IGNITOR		
С	ABB FIBER OPTIC FLAME SCANNER		
D	DAMPER DRIVE	IN TO OPEN	16"
E	SIGHT TUBE		
F	INNER AIR ZONE DAMPER	PUSH TO OPEN	6"
G1	TIP THERMOCOUPLE JUNCTION BOX		
G2	BODY THERMOCOUPLE JUNCTION BOX		



From:

Dean Wood

To:

sal@advancedburner.com

Subject:

Fwd: U2 Outage F Burner Inspection

Sal,

This is a raw copy of the preliminary report from last weekends outage inspection. No editing, no punches pulled. There are more photos but these are the most significant. If you need more information, please contact Garry Christensen at garry-c@ipsc.com and copy me on the e-mail. Garry will be taking the lead on burner issues as Phil Hailes will be focusing on Turbine and Generator issues.

We have not quantified air flows on the Unit 2 F row yet but will work on that.

Anything you can add to help us solve these issues is appreciated.

Thanks,

Dean

>>> Aaron Nissen 10/15 8:45 PM >>> U2 Outage F Burner Inspection Summary

Reason- F3 Burner Fire (which resulted in the isolation of this new ABT burner)
When-Inspection conducted during U2 Boiler WW Tube Leak (on 2 1/2 floor) 10/12/2005
What-Removed burner elbows to inspect coal nozzles & tips and repair damage found
Inspection- Phil Hales & Aaron Nissen

FOUND: (referenced attached pics)

F3 Burner- major meltdown of the coal nozzle into the outer sleeve. 40% of the entire length of the nozzle has melted (bottom right). Due to the damage on the outer sleeve, the burner assembly needs to be replaced (during next Spring U2 Outage), although the air register assemblies look intact. Coal Nozzles- coal erosion found in the 3:00 & 9:00 clock positions on all nozzles (below where the X-vane cross piece rides)

This erosion is within the first 18" of the nozzle. F6 nozzle, left side, had a hole eroded completely through.

Nozzle tips- major erosion and holes in the flowered tip (designed for coal staging), plus cracks in the "high tech alloy". Near impossible to weld up and due to high temps from furnace flame, impractical to RTV or nordbak/ceramic patch. Also the weld interface from the nozzle to the tip has creep damage (warped)

Coal Elbows- major erosion at the top of the nozzle. F1 & F2 already had eroded thru the original ceramic lining and thru the elbow material requiring external patches. F2 had a hole already in the external patch. F4 & F5 had holes eroded in the ceramic, but not yet thru the elbow metal. F6 has not yet eroded through the ceramic.

REPAIRS:

Coal Nozzles- ALL (except F3) coal nozzle sidewalls weld repaired at (3:00 & 9:00 clock position)
Coal Elbows- ALL (except F3) elbows were ceramic (nordbak) repaired at the very top (holes in ceramic)
F2 also had an external patch installed due to a hole in the 1st external patch

NOTE: Place F pulv back in-service LAST (to allow ceramic Nordbak to cure in elbows- 24 hr cure time) ALSO- Maintenance closed several of the Burner Isolation gates locally (originally weren't closed as part of the clearance). Operations needs to verify all iso gates are open before placing pulv I/S (F1& F2 were closed, need to check others.

NOTE: U2 F Pulv will be coming O/S in the next several weeks for major overhaul and NEW rotating throats

However, during this time will be taking primary air flow measurements to check line velocities.

FUTURE: U2 Spring Outage- F3 burner will need to be replaced, as well as all other coal nozzles, preferably

ceramic lined and new designed nozzle tips. Elbows also needed revamped or better yet replaced (so have

one spare set to modify and rotate), also X-vanes needed replaced or modified (they aren't doing their job).

Final Inspection Report will follow

rest of pics located are at the following address:
N:\Current\Outages\2005 Outages\U2 2005 Unscheduled Outages\
05-1010 U2 external Tube Leak 2.5 NW LVL\Burner Row U2 F Inspection\pics

CC:

Christensen, Garry